

September 16, 2020

Brief Early Information Update: Fifth Five-Year Review for the McCormick & Baxter Superfund Site

Anne Christopher, EPA REGION 10 REMEDIAL PROJECT MANAGER

- What is a Five-Year Review?
- McCormick & Baxter Overview
- Status of Fifth Five-Year Review for McCormick & Baxter
- Request for Information


What is a Five-Year Review?

An assessment of the remedy to make sure it is still protective of human health and the environment.

Done every five years after construction starts



Source: Oregon Department of Environmental Quality



Where is McCormick & Baxter?

McCormick & Baxter 101

History

Former creosote wood treating facility.

Contamination

 Wood-treating chemicals caused contamination in the soil, groundwater, and sediment.

Final Remedy

- Groundwater barrier wall
- Soil cap
- Sediment cap

Simplified Timeline

1994: EPA adds Site to National Priorities List

1996: DEQ & EPA issue Final Cleanup Plan (also called Record of Decision or ROD)

2001: First Five-Year Review


2005: Cleanup activities complete

2006: Second Five-Year Review

2011: Third Five-Year Review


2016: Fourth Five-Year Review

2021: Fifth Five-Year Review (in progress)



Useful Items to Review

- ✓ 2016 Fourth Five-Year Review
- √ 2019 <u>McCormick & Baxter Annual Operation & Maintenance</u>
 (O&M) Report
- ✓ EPA's McCormick & Baxter Website
 - www.epa.gov/superfund/mccormick-baxter-portland



McCormick & Baxter Fifth Five-Year Review Status

McCormick & Baxter Fifth Five-Year Review Request for Information

Do you have information on how the remedy is working?

Vessels that might have damaged the sediment cabs



Any damage to signage or fencing?

Other information?

By May 31, 2021

Please contact:

Anne Christopher, EPA | Christopher.Anne@epa.gov | 503-326-6554 Sarah Miller, DEQ | Sarah.Miller@state.or.us | 503-229-5040

Questions?

Anne Christopher, EPA | <u>Christopher.Anne@epa.gov</u> | 503-326-6554 Sarah Miller, DEQ | <u>Sarah.Miller@state.or.us</u> | 503-229-5040